

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2296 From entrance to location




Photo # 2297 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2298 Location



Photo # 2299 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2300 Location



Photo # 2301 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2302 Location



Photo # 2303 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2304 Location



Photo # 2305 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2306 Tank capacity incorrect



Photo # 2307 Tank capacity

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2308 Tank capacity incorrect



Photo # 2309 Tank capacity