

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/07/2025

Submitted Date:

05/09/2025

Document Number:

719000035

**FIELD INSPECTION FORM**

Loc ID: 306755 Inspector Name: GARCIA, CHARLES On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

17 Number of Comments  
1 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263013	WELL	SI	01/01/2025	CBM	067-08704	TINKER FEDERAL 2	SI

**General Comment:**

Inspection Report Summary  
On 05/07/25 | Inspector Charles Garcia conducted an on-site inspection.  
Location: Tinker Federal 2  
Operator: Simcoe LLC  
API#: 067-08704  
County: LaPlata  
Well shut in status and appears to be in reclamation Process

Location			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	<a href="#">Sign at entrance of location</a>		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<a href="#">Contact # 970-247-6916</a> <a href="#">Emergency #911</a>		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	<a href="#">Combustible/potentially combustible within 25' of wellheads, tanks and separators Rule 610.k</a>		
Corrective Action:			Date:
Type	OTHER		
Comment:	<a href="#">All 4 sides of location have signs seeded area KEEP OUT</a>		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	<a href="#">4 ft barbwire</a>		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	<a href="#">Cattel panels</a>		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	<a href="#">Catel panles</a>		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Flow Line # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked # 0			
Comment:	<a href="#">Dead men have been removed</a>		
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Well Head		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Eletrical Panels		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Last Calibration 02/11/25		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		
Comment:	Partially buried 21 BBL tank				
Corrective Action:					Date:

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:	It appears, paint peeled, visible corrosion/bare metal "Inspect, maintain/paint tank per Rule 609.b"	
Corrective Action:	"Inspect, maintain/paint tank per Rule 609.b"	Date: 07/09/2025

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 263013 Type: WELL API Number: 067-08704 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Satisfactory last reported production Dec 2024",

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 07/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404210082	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056681">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056681</a>
719000041	Location Pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056665">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056665</a>