

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2025

Submitted Date:

05/19/2025

Document Number:

696307622

FIELD INSPECTION FORM

Loc ID: 437037 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10670
Name of Operator: BISON IV OPERATING LLC
Address: 518 17TH STREET SUITE 1800
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|--------------------|-------------------------------------|
| Buck, Paul | 303-882-5868 | pbuck@bisonog.com | ALL INSPECTIONS |
| Milne, Rachel | 720-370-8580 | rmilne@bisonog.com | |
| Garza, Tarah | 970-514-3581 | tgarza@bisonog.com | Environmental Compliance Specialist |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 437036 | WELL | SI | 08/01/2023 | OW | 123-39389 | Pronghorn 11-41-24HNC | SI |

General Comment:

This is a Well and Tank Battery Field Compliance Audit

| Location | | | |
|--|---|--------|------------------|
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign Still reflects previous Operator, see photos | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | | Date: 06/09/2025 |
| Type | CONTAINERS | | |
| Comment: | Adequate | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | 500 BBL Produced Water Tank (SE TANK) - NFPA Label missing; see photos | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | | Date: 06/09/2025 |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | | | Date: _____ |
| Corrective Action: | | | |
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Stained Soil at Wellhead; see photos | | |
| Corrective Action: | E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905. Contact ECMC EPS staff. | | Date: 05/23/2025 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unmarked Risers at Separators; see photos | | |
| Corrective Action: | Comply with Rule 1105 | | Date: 05/23/2025 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panels | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Emission Control Device # 4 | | | corrective date |
| Comment: | | | |

| | | | |
|-----------------------------------|----------------------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: VRT | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 437036 Type: WELL API Number: 123-39389 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI - Since 08.01.2023

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|--|--------|------------|
| Routine Field Compliance Audit | petrie | 05/19/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404209397 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7055991 |
| 696307623 | Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7055983 |