

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2025

Submitted Date:

05/19/2025

Document Number:

708906516

**FIELD INSPECTION FORM**Loc ID 334612 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10844

Name of Operator: QB ENERGY OPERATING LLC

Address: 1001 17TH STREET SUITE 1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

29 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Longworth, Mike		mike.longworth@state.co.us	
QB Energy		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270111	WELL	PR	10/09/2008	GW	045-09455	BENZEL 1-16C (P1W)	PR
270112	WELL	PR	05/30/2004	GW	045-09456	BENZEL 1-16D (P1W)	PR
270179	WELL	PR	10/27/2003	GW	045-09484	SHAEFFER 12-1C (P1W)	PR
270180	WELL	PR	05/31/2004	GW	045-09485	SHAEFFER 12-1D (P1W)	PR
271339	WELL	PR	05/25/2004	GW	045-09867	BENZEL 1-15C	PR
271340	WELL	PR	04/28/2004	GW	045-09868	SHAEFFER 12-2A (P1W)	PR

**General Comment:****CECMC Inspection/Audit Report Summary**

On 05/14/2025 at approximately 15:30 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location # 334612 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Equipment - Multiple unused flowlines do not comply with CECMC rules with a CA date of 05/26/2025
2. Tanks & Berms - Multiple holes in secondary containment liner/liner needs maintenance with a CA date of 06/08/2025
3. Stormwater - Stockpiled soils with no BMP's with a CA date of 06/03/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Upon the Director's approval of a Form 9 the Buying Operator will have 60 days to replace or update all signs at the Oil and Gas Location so that the signs comply with Rule 605.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signs at separators		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-2615	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris - please refer to photo logs		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Other	# 5		
Comment:	Multiple unused flowlines do not comply with CECMC rules		
Corrective Action:	Comply with CECMC 600 & 1100 series rules	Date:	05/26/2025
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank No FORM 4 SUNDRY for equipment/not in compliance with CECMC rules		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLS	STEEL AST		,
Comment:	Tank equipped with telemetry				

Corrective Action:		Date:	
<b>Paint</b>			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Metal	Inadequate	Walls Insufficient	Base Insufficient
Comment:		Multiple holes in secondary containment liner/liner needs maintenance	
Corrective Action:		The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.	
		Date: 06/08/2025	
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 270111 Type: WELL API Number: 045-09455 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270112 Type: WELL API Number: 045-09456 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270179 Type: WELL API Number: 045-09484 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270180 Type: WELL API Number: 045-09485 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 271339 Type: WELL API Number: 045-09867 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 271340 Type: WELL API Number: 045-09868 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Other	Fail			Stockpiled soils with no BMP's
		Culverts				
Berms						
		Compaction				
Compaction						Small amount of light compaction
		Gravel				Sparse to none
		Ditches				
Rip Rap						
				Material Handling And Spill Prevention		Chemical tank containment
Gravel						Sparse to none in most areas

Comment: 1. Stockpiled soils with no BMP's (along lease road approximately 2/10th of a mile from entrance to location)

Additionally there is various debris within the soil stockpile - please refer to photo log

Corrective Action: **Comply with CECMC Stormwater rules**

Date: 06/03/2025

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Please refer to Equipment, Tanks & Berms & Stormwater for corrective actions & also refer to Signs/Marker, Housekeeping & Equipment for comments.	smelserw	05/19/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404210101	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056714">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056714</a>
708906517	Inspection/Audit 708906516 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056712">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056712</a>
708906518	Inspection/Audit 708906516 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056713">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056713</a>