

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2025

Submitted Date:

05/20/2025

Document Number:

719000077

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: GARCIA, CHARLES On-Site Inspection   
 325300 \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10133  
 Name of Operator: HILCORP ENERGY COMPANY  
 Address: P O BOX 61229  
 City: HOUSTON State: TX Zip: 77208

**Findings:**

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		FarmingtonRegulatoryTechs@hilcorp.com	<a href="#">All Inspections 6/21/2022</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214515	WELL	PR	01/01/2022	CBM	067-06118	SQUIRES 1	PR
412454	WELL	PR	12/06/2009	CBM	067-09762	SQUIRES 4	PR

**General Comment:**

[Inspection Report Summary](#)  
 On 5/16/25 | Inspector Charles Garcia conducted an on-site inspection.  
 Location: SQUIRES #4, SQUIRES #1  
 Operator:HILCORP ENERGY COMPANY  
 #1 API#: 067-06118  
 #4 API#: 067-09762  
 County: LaPlata

Location			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	LOCATION SIGN		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	5050-324-5170 911 EMERGENCY		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	LUBE OIL LEAK ON ENGINE SKID		
Corrective Action:	IMMEDIATE RESPOND TO LUBE OIL LEAKING ON GROUND CLEAN UP FREE FLUIDS RULE 907 IF DETERME MORE THEN 1 BBL CONTACT SW CPS JASON KOSOLA		Date: <u>05/22/2025</u>
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Prime Mover			# 2
Comment:	GAS ENGINE FOR PRIME MOVER ON THE SQUIRES #4 LEAKING OIL STARTING IMPACTING SOIL AROUND PUMP JACK SEE PICTURES #3, #4 NO SPILL RESPONE MATERIALS IN USE		
Corrective Action:	MAINTAIN ENGINE RULE 608.e		Date: <u>06/20/2025</u>
Type: Ancillary equipment			# 2
Comment:	OIL TANK FOR PRIME MOVER WIYH SPILL PREVENTION ON#4 OIL TANK FOR PRIME MOVER ON THE #1 HAS NO SPILL PREVENTION		
Corrective Action:			Date:
Type: Other			# 2
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Ancillary equipment			# 1
Comment:	TELEMETRY EQUIPMENT		

Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	METER HOUSE LAST CALIBRATION 2/20/05 ON #1 AND #4		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	2 DEADMAN MARKERS ON GROUND		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 214515 Type: WELL API Number: 067-06118 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date: <span style="border-bottom: 1px solid black; display: inline-block; width: 50px;"></span>

**BradenHead**

Date of Last Brhd Test: 06/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412454 Type: WELL API Number: 067-09762 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date: <span style="border-bottom: 1px solid black; display: inline-block; width: 50px;"></span>

**BradenHead**

Date of Last Brhd Test: 06/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404211157	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057901">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057901</a>
719000080	LOCATION PICTURES	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057891">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057891</a>