

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2025

Submitted Date:

05/20/2025

Document Number:

719000078

**FIELD INSPECTION FORM**Loc ID 311965 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		FarmingtonRegulatoryTechs@hilcorp.com	All Inspections 6/21/2022
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216476	WELL	PR	08/12/1997	CBM	067-08082	T.H. 32-7 12-1	PR
290382	WELL	PR	11/09/2007	CBM	067-09361	TIFFANY 32-7-12 8	PR

**General Comment:**

Inspection Report Summary  
On 5/16/25 I Inspector Charles Garcia  
conducted an on-site inspection.  
Location: TIFFANY 32-7-12 8 AND T.H.32-7 12-1  
Operator:HILCORP ENERGY COMPANY  
TIFFANY 32-7-12 8 API#: 067-09361  
T.H. 32-7 12-1 API#: 067-08082  
County: LaPlata

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	LOCATION SIGNS AT WELLHEADS		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	505-324-5170 911 EMERGENCY	
Corrective Action:		Date:

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	LARGE PILE OF GRAVEL AND UNUSED EQUIPMENT SEE PIC #5		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	CATTLE PANLES		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	OIL TANK WITH SPILL PREVENTION FOR PRIME MOVER ON T.H. 32-7 12-1		
Corrective Action:		Date:	

Type: Other	# 2	
Comment:	METER HOUSES LAST CALIBRATION TIFFANY 32-7-12 8 5/10/25 TH 32-7 12-1 5/10/25	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 2	
Comment:	SEPARATOR ON TIFFANY 32-7-12 8 HAS LEAK ON GATHERING LINE GOING INTO SEPARATOR BUILDING SEE PICUTURE #7	
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date: 05/22/2025
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:	3 DEADMEN UNMARKED	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	GAS	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:	3 DEADMEN UNMARKED	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	TELEMETRY EQUIPMENT	
Corrective Action:		Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	216476	Type:	WELL	API Number:	067-08082	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:		06/13/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	290382	Type:	WELL	API Number:	067-09361	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:		06/13/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404211161	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057905">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057905</a>
719000081	LOCATION PICTURES	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057892">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057892</a>