

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2025

Submitted Date:

05/20/2025

Document Number:

719000088

**FIELD INSPECTION FORM**

Loc ID 325466 Inspector Name: GARCIA, CHARLES On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

**Findings:**

11 Number of Comments  
1 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
,		FarmingtonRegulatoryTechs@hilcorp.com	<a href="#">All Inspections 6/21/2022</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214812	WELL	PR	06/11/2001	CBM	067-06416	TIFFANY C 1	PR
419641	WELL	PR	12/14/2010	CBM	067-09838	TIFFANY 2 3	PR

**General Comment:**

[Inspection Report Summary](#)  
On 5/19/25 | Inspector Charles Garcia conducted an on-site inspection.  
Location: TIFFANY C #1 API# 067-06416  
TIFFANY #2-3 API# 067-09838  
Operator:HILLCORP ENERGY COMPANY  
County: LaPlata

Location			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGNS AT WELLHEADS		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	505-324-5170 911 EMERGENCY		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Ancillary equipment	# 2	corrective date	
Comment:	OIN TANKS FOR PRIME MOVERS WITH SPILL PREVENTION ON C #1 #2-3 TANK HAS NO SPILL PREVENTION		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Prime Mover	# 2		

Comment:	GAS		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Other	# 2			
Comment:	METER HOUSE LAST CALIBRATION TIFFANY C#1 NO CARD FOUND TIFFANY #2-3 1/27/25		Date:	
Corrective Action:	PROVIDE CALIBRATION RECORD FOR TIFFANY C #1		Date:	06/20/2025
Type: Flow Line	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 5			
Comment:	4 MARKERS ARE ON GROUND		Date:	
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 214812 Type: WELL API Number: 067-06416 Status: PR Insp. Status: PR

**Producing Well**

Comment:	<input style="width: 95%;" type="text"/>	
Corrective Action:	<input style="width: 95%;" type="text"/>	Date: <input style="width: 50%;" type="text"/>

**BradenHead**

Date of Last Brhd Test: 06/19/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419641 Type: WELL API Number: 067-09838 Status: PR Insp. Status: PR

**Producing Well**

Comment:	<input style="width: 95%;" type="text"/>	
Corrective Action:	<input style="width: 95%;" type="text"/>	Date: <input style="width: 50%;" type="text"/>

**BradenHead**

Date of Last Brhd Test: 06/19/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404211251	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057976">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057976</a>
719000095	location pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057965">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057965</a>