



ECMC
Environmental
Field Inspection



1415 Corp Gas Unit 2 Wellhead
20-May-25 03:36:18 PM
ECMC Environmental Inspection

An excavation remains open in the area of the former wellhead. Orange construction fencing surrounds the open excavation. An unmarked soil stockpile was observed on location; no liner was visible.



1415 Corp Gas Unit 2 Wellhead
© 20-May-25 03:36:54 PM
ECMC Environmental Inspection

ECMC
Environmental
Field Inspection



Two risers are visible within the excavation. Debris is visible at the base of the excavation.

WGS84 $\pm 14\text{ft}$ 40.14140, -104.86363 $\wedge^m_{\pm 4\text{m}}$ 1510 $\triangle^{\circ, T}_{\pm 12}$ W263



ECMC
Environmental
Field Inspection



1415 Corp Gas Unit 2 Wellhead
© 20-May-25 03:37:55 PM
ECMC Environmental Inspection

An unmarked soil stockpile was observed on location; no liner was visible.