

WGS84 $\pm 11\text{ft}$ 40.11407, -104.94631 $\wedge^m_{\pm 3\text{m}}$ 1516 $\triangle^{\circ, T}_{\pm 11}$ E91



Donald B Smith Unit 1 Flowline
© 16-May-25 10:35:15 AM
ECMC Environmental Inspection

Approximate spill location. Excavation has been backfilled.

WGS84 $\pm 13\text{ft}$ 40.11422, -104.94593 $\wedge^m_{\pm 3\text{m}}$ 1516 $\triangle^{\circ, T}_{\pm 11}$ SW229



KIK
KIK INDUSTRIES COMPANY, INC.
In Case of Emergency call
1031 825-4822 OR 911
DANGER - HIGH VOLTAGE - WELL HEAD
N. 15th St. - 111 25th St. - 111
WELD COUNTY, COLORADO
THIS UNIT
STARTS AUTOMATICALLY

ECMC
Environmental
Field Inspection



Donald B Smith Unit 1 Flowline
© 16-May-25 10:36:17 AM
ECMC Environmental Inspection

Signage with emergency contact number is visible

WGS84
±18ft

40.11416, -104.94604

m
±5m

1517

°T
±11

NE38



Donald B Smith Unit 1 Flowline
© 16-May-25 10:36:50 AM
ECMC Environmental Inspection

ECMC
Environmental
Field Inspection



Stained soil is visible around the wellhead.

WGS84 40.11417, -104.94597 m 1517 NE56
±10ft ±3m ±11



ECMC
Environmental
Field Inspection 

Donald B Smith Unit 1 Flowline
© 16-May-25 10:38:59 AM
ECMC Environmental Inspection

A strong petroleum hydrocarbon odor was observed when the stained soil was disturbed.

WGS84
±9ft

40.11417, -104.94601

▲
m
±4m

1517

▲ °, T
±11

N1



ECMC
Environmental
Field Inspection



Donald B Smith Unit 1 Flowline
© 16-May-25 10:39:05 AM
ECMC Environmental Inspection

A strong petroleum hydrocarbon odor was observed when the stained soil was disturbed.

WGS84 $\pm 16\text{ft}$ 40.11418, -104.94612 $\pm 4\text{m}$ 1516 ± 11 °, T W283



ECMC
Environmental
Field Inspection



Donald B Smith Unit 1 Flowline
© 16-May-25 10:39:18 AM
ECMC Environmental Inspection

Looking at lease road from facility. The lease road is currently passable by vehicle but is overgrown with weeds.