

WGS84 40.09307, -104.88597

m  
±4m

1526

°T  
±10

NW338



ECMC  
Environmental  
Field Inspection



Pete Montoya B1-#2  
© 16-May-25 01:09:00 PM  
ECMC Environmental Inspection

A drainage ditch is visible in the foreground. The open excavation is visible in the background on the left side of the picture; the stockpile liner is visible in the background on the right side of the picture.

WG304 ±8ft 40.09323, -104.88603  $\wedge$  m ±3m 1527  $\triangle$  °, T ±11 NW309



ECMC  
Environmental  
Field Inspection



Pete Montoya B1-#2  
© 16-May-25 01:10:09 PM  
ECMC Environmental Inspection

The previously observed stockpile has been removed from location; however, the liner under the stockpile remains on location.

WGS84  $\pm 9\text{ft}$  40.09336, -104.88628  $\Delta$   $\pm 3\text{m}$  1527  $\text{°}, \text{T}$   $\pm 12$  SW195



ECMC  
Environmental  
Field Inspection



Pete Montoya B1-#2  
© 16-May-25 01:10:31 PM  
ECMC Environmental Inspection

An excavation remains open at the spill location. Salt crusting is visible. Debris has collected within the excavation and obscures visibility of the floor and portions of the sidewalls. Weeds are visible within the excavation. Orange construction fencing has been installed but has fallen and does not surround the entire perimeter of the excavation.

WGS84  $\pm 12\text{ft}$  40:09331, -104.88629  $\pm 3\text{m}$  1526  $\pm 12$  °,T SW199



ECMC  
Environmental  
Field Inspection



Pete Montoya B1-#2  
© 16-May-25 01:10:49 PM  
ECMC Environmental Inspection

Salt crusting is visible on the excavation sidewalls. Debris has collected within the excavation and obscures visibility of the floor and portions of the sidewalls.

WGS84  $\pm 12\text{ft}$  40.09319, -104.88483  $\Delta^m_{\pm 3m}$  1525  $\triangle^{\circ,T}_{\pm 12}$  E76



ECMC  
Environmental  
Field Inspection



Pete Montoya B1-#2  
© 16-May-25 01:12:50 PM  
ECMC Environmental Inspection

Weeds are visible adjacent to the wellhead.

WGS84  $\pm 11\text{ft}$  40.09324, -104.88472  $\pm 3\text{m}$  1526  $\pm 11$  °T S188



ECMC  
Environmental  
Field Inspection



Pete Montoya B1-#2  
© 16-May-25 01:13:08 PM  
ECMC Environmental Inspection

Emergency contact number is not visible on the signage.

WGS84  
±9ft

40.09317, -104.88458

m  
±3m

1524

°T  
±12

E82



ECMC  
Environmental  
Field Inspection



Pete Montoya B1-#2  
© 16-May-25 01:13:32 PM  
ECMC Environmental Inspection

Debris/unused equipment is visible adjacent to ancillary equipment.