

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/20/2025

Submitted Date:

05/20/2025

Document Number:

716301005

FIELD INSPECTION FORMLoc ID 309409 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------------|--------------|----------------------------|---------------------------------|
| D DYKE, TRACY | 719-846-7898 | tracy.dyke@enrllc.com | Insp. w/ca's |
| Distribution, Evergreen | 719-846-7898 | cogcc.evergreen@enrllc.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 294539 | WELL | WO | 06/13/2011 | GW | 071-09495 | UTE CANYON 12-3 | WO |

General Comment:

Inspected Facilities

Facility ID: 294539

Type: WELL

API Number: 071-09495

Status: WO

Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: PHOTO 1: DEVELOPMENT ENTRANCE OFF COUNTY ROAD/ NO COMBONATION
Location is not accessible during normal business hours. Provide key, combinations, or
alternate method of access to comply with rule 204. CA DATE 5/22/2025.

Corrective Action: Provide key, combinations, or alternate method of access to comply with rule 204.

Date: 05/22/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404212209 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7059148 |
| 716301006 | INSP. PHOTOS | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7059128 |