

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404219311

Date Received:
05/28/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>QB Energy</u>		<u>ecmc.inspections@qb-energy.com</u>
<u>Haverkamp, Curtis</u>		<u>curtis.haverkamp@state.co.us</u>
<u>Katz, Aaron</u>		<u>aaron.katz@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708906369
Inspection Date: 04/28/2025 FIR Submit Date: 04/28/2025 FIR Status:

Inspected Operator Information:

Company Name: QB ENERGY OPERATING LLC Company Number: 10844
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334666

Location Name: JUNIPER-67S92W Number: 1SWSW County:
Qtrqtr: SWS Sec: 1 Twp: 7S Range: 92W Meridian: 6
W
Latitude: 39.472150 Longitude: -107.623020

FACILITY - API Number: 05-045-00 Facility ID: 334666

Facility Name: JUNIPER-67S92W Number: 1SWSW
Qtrqtr: SWS Sec: 1 Twp: 7S Range: 92W Meridian: 6
W
Latitude: 39.472150 Longitude: -107.623020

CORRECTIVE ACTIONS:

1 CA# 204442

Corrective Action: Comply with CECMC wildlife rules Date: 05/05/2025

Response: CA COMPLETED Date of Completion: 05/13/2025

Covered opening in corrugated piping.

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 204443

Corrective Action: Comply with multiple CECMC 400 series rules & additionally contact CECMC Engineering Group to discuss observed compliance issues.

Date: 05/28/2025

Response: CA COMPLETED

Date of Completion: 05/27/2025

Operator
Comment:

Upon receiving this FIR, QB staff performed an investigation of this well and determined that the bradenhead valve was buried and, as a result, the intermediate casing had inadvertently been tested and reported as the bradenhead for the reporting years of 2022 through 2024. The bradenhead valve was uncovered and a test of both the bradenhead and intermediate casing was performed on May 20, 2025 and a Form 17 documenting this test was submitted to ECMC (Doc ID 404212985). An updated wellbore diagram accurately depicting this well was attached to a Form 4 submitted to ECMC on 5/27/25.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Justin Johnson

Signed:

Title: Compliance

Date: 5/28/2025 8:51:12 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404219326	Plumbed and uncovered valve
404219334	Covered open piping.

Total Attach: 2 Files