

WGS84 $\pm 9\text{ft}$ 40.17861, -104.99500 $\wedge^m_{\pm 3\text{m}}$ 1499 $\triangle^{\circ, T}_{\pm 11}$ E85



ECMC
Environmental
Field Inspection



Adler 22-34 Wellhead
© 22-May-25 10:02:07 AM
ECMC Environmental Inspection

Looking at the former spill location from the end of the partially remaining access road. The excavation has been backfilled. Crops appear to have been planted.