

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2025

Submitted Date:

05/28/2025

Document Number:

717100219

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Rollins, Grace _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Brown, Kari		kari.oakman@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486100	SPILL OR RELEASE	AC	02/16/2024		-	Adler 22-34 Wellhead	EI

General Comment:

ECMC Field Inspection Report Summary
This is an environmental inspection to determine progress on Spill ID 486100 and Remediation Project # 32527. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 486100
Spill Name: Adler 22-34 Wellhead
Remediation Project #: 32527
Wellhead API #: 05-123-30454
Reported Date of Discovery: 01/24/2024
Date of Inspection: 05/22/2025

Spill is located within or adjacent to:
-Crop land (immediately adjacent, all directions)
-Bald Eagle Roost Site High Priority Habitat (~420 ft south-southeast)

Current site status:
-Excavation has been backfilled.
-Crops appear to have been planted.

See attached corrective actions. A Form 19 – Supplemental is required.

Inspected Facilities

Facility ID: 486100 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure. The Form 19 — Supplemental Report for closure was due by 04/23/2024.

Corrective Action: Operator shall submit delinquent form(s) for this project. Date: 06/11/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100220	ECMC Photo Log - Adler 22-34 Wellhead - 05.22.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7068293