

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2025

Submitted Date:

05/28/2025

Document Number:

717100221

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Rollins, Grace On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Findings:

5 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
,		ECMCInspections@Oxy.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	
Brown, Kari		kari.oakman@state.co.us	
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486008	SPILL OR RELEASE	AC			-	Mullet 6-21A/UP42 O SA	EI

General Comment:

[ECMC Field Inspection Report Summary](#)


This is an environmental inspection to determine progress on Spill ID 486008 and Remediation Project # 28966. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 486008
 Spill Name: Mullet 6-21A/UP42 O SA
 Remediation Project #: 28966
 Facility ID: 470881
 Reported Date of Discovery: 02/02/2024
 Date of Inspection: 05/21/2025

Spill is located within or adjacent to:
 -Residential building unit (~175 ft southeast)
 -Wetlands (Riverine) and irrigation canal (~430 ft west)
 -Crop land (immediately adjacent, all directions)

Current site status:
 -The excavation at the spill location has been backfilled.
 -Risers are visible in the approximate area of the spill.
 -A network of monitoring wells completed as flush mounts was visible on location.
 -Areas of the former facility footprint appear to have been tilled; however, the approximate spill location does not appear to have been tilled.

See attached corrective actions. A Form 19 – Supplemental is required.



Inspected Facilities

Facility ID: 486008 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure. The Form 19 — Supplemental Report for closure was due by 05/02/2024.

Corrective Action: Operator shall submit delinquent form(s) for this project. Date: 06/11/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100222	ECMC Photo Log - Mullet 6-21A/UP42 O SA - 05.21.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7068360