

Inspection Photos
Location: Red Rocks 35-15
Location ID: 481116
API # 05-071-09919



Photo 1 –Well placard

Photo 2 – Noxious weeds and undesirable plants observed at the time of inspection

Inspection Photos
Location: Red Rocks 35-15
Location ID: 481116
API # 05-071-09919



Photo 3 – Noxious weeds and undesirable plants observed at the time of inspection

Photo 4 – Oil stained soils observed on location at Long 37.478259 Lat -103.543744

Inspection Photos
Location: Red Rocks 35-15
Location ID: 481116
API # 05-071-09919



Photo 5 – Stormwater/erosion

Photo 6 – Unused poly pipe at entrance to location