

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/28/2025

Submitted Date:

05/28/2025

Document Number:

696307672

FIELD INSPECTION FORM

Loc ID 461774 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10670
Name of Operator: BISON IV OPERATING LLC
Address: 518 17TH STREET SUITE 1800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Garza, Tarah	970-514-3581	tgarza@bisonog.com	Environmental Compliance Specialist
Buck, Paul	303-882-5868	pbuck@bisonog.com	ALL INSPECTIONS
Milne, Rachel	720-370-8580	rmilne@bisonog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
461774	Location	AC			-	Fabrizius 33-12, 14, 42, 44	SI

General Comment:

[This is a Tank Battery Field Compliance Audit](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

Type	#		corrective date
Vertical Heater Treater	# 2		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	<input type="text"/>				

Corrective Action:						Date:				
<u>Paint</u>										
Condition		Adequate								
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:						Shares berm with the Crude Oil Tanks				
Corrective Action:								Date:		
Contents		#	Capacity		Type		Tank ID		SE GPS	
PRODUCED WATER		1	100 BBLs		FIBERGLASS AST					
Comment:										
Corrective Action:								Date:		
<u>Paint</u>										
Condition		Adequate								
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:						Shares berm with the Crude Oil Tanks				
Corrective Action:								Date:		
Contents		#	Capacity		Type		Tank ID		SE GPS	
PRODUCED WATER		1	500 BBLs		STEEL AST					
Comment:										
Corrective Action:								Date:		
<u>Paint</u>										
Condition		Adequate								
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:						Shares berm with the Crude Oil Tanks				
Corrective Action:								Date:		
Contents		#	Capacity		Type		Tank ID		SE GPS	

CRUDE OIL	2	500 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 461774 Type: Location API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696307673	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7068738