

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



May 28, 2025 at 3:22:56 PM
CO

Photo # 3762 From entrance to location



May 28, 2025 at 3:23:02 PM
CO

Photo # 3763 From entrance to location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755




Photo # 3764 Location



Photo # 3765 Location



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 3766 Location



Photo # 3767 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



May 28, 2025 at 3:27:17 PM
CO

Photo # 3768 Location



May 28, 2025 at 3:28:11 PM
CO

Photo # 3769 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 3770 Location



Photo # 3771 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 3772 Location



Photo # 3773 Location



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 3774 Location



Photo # 3775 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 3776 Location



Photo # 3777 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 3778 Location



Photo # 3779 Staining near tank battery

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 3780 Emergency contact # on wellhead sign incorrect/# is disconnected & not in service



Photo # 3781 Emergency contact # on wellhead sign incorrect/# is disconnected & not in service

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 3782 Emergency contact # on wellhead sign incorrect/# is disconnected & not in service