

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2025

Submitted Date:

05/29/2025

Document Number:

707801614

FIELD INSPECTION FORM

Loc ID 437879 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 20 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Ryan Snyder		rlsnyder@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437880	WELL	PR	08/01/2020	GW	045-22451	Federal 14/15-8-21	PR
438167	WELL	PR	08/01/2020	GW	045-22454	Federal 14/15-6-21	PR
438168	WELL	PR	08/01/2020	GW	045-22455	Federal 14/15-3-21	PR
438169	WELL	PR	08/01/2020	GW	045-22456	Federal 14/15-1-21	PR
438170	WELL	PR	08/01/2020	GW	045-22457	Federal 14/15-5-21	PR
438171	WELL	PR	08/01/2020	GW	045-22458	Federal 14/15-2-21	PR
438172	WELL	PR	08/01/2020	GW	045-22459	Federal 14/15-4-21	PR
438179	WELL	SI	02/01/2024	GW	045-22460	Federal 14/15-7-21	PA

General Comment:

CECMC Inspection Report Summary

On Wednesday 5/21/2025, I, Inspector Scott Ramsey, conducted a routine inspection/audit at TEP FED well pad 21B, at Location # 437879 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. No evidence of a tracking pad on location.

During this inspection the following compliance issues were observed:

1. A calibration card shows lack of calibration compliance. (see photos)
2. Cataflow inside tank battery containment.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:		
Type	OTHER	
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.	
Corrective Action:		Date:
Type	TANK LABELS/PLACARDS	
Comment:		
Corrective Action:		Date:
Type	WELLHEAD	
Comment:		
Corrective Action:		Date:
Type	BATTERY	
Comment:		
Corrective Action:		Date:
Type	CONTAINERS	
Comment:		
Corrective Action:		Date:

Emergency Contact Number:		
Comment:	<input type="text" value="911/970-285-9377"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Good Housekeeping:		
Type	OTHER	
Comment:	Cataflow inside tank battery containment. No ancillary equipment that has potential ignition sources will be installed or used inside the secondary containment area.	
Corrective Action:	Remove ancillary equipment that has potential ignition sources from secondary containment.	Date: <u>07/04/2025</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containments		
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:

Type: Emission Control Device	# 1		
Comment:	Running at time of inspection and metered.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Cataflo heater see houskeeping for C/A		
Corrective Action:			Date:
Type: Gas Meter Run	# 9		
Comment:	A calibration card shows lack of calibration compliance. (see photos)		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 06/30/2025
Type: Bird Protectors	# 13		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Air compressor		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLS	HEATED STEEL AST		,
Comment:	2 tanks are not heated				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	500 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	437880	Type:	WELL	API Number:	045-22451	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	438167	Type:	WELL	API Number:	045-22454	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	438168	Type:	WELL	API Number:	045-22455	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	438169	Type:	WELL	API Number:	045-22456	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	438170	Type:	WELL	API Number:	045-22457	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	438171	Type:	WELL	API Number:	045-22458	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	438172	Type:	WELL	API Number:	045-22459	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	438179	Type:	WELL	API Number:	045-22460	Status:	SI	Insp. Status:	PA
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none
		Culverts				
		Gravel				Sparse to none
		Ditches				
Berms						

Comment: Places with sparse to no gravel & light compaction are present on lease road and location. Sparse to no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801615	Photro log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7072659