

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/28/2025

Submitted Date:

05/28/2025

Document Number:

696307676

FIELD INSPECTION FORM

Loc ID 461134 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10670
 Name of Operator: BISON IV OPERATING LLC
 Address: 518 17TH STREET SUITE 1800
 City: DENVER State: CO Zip: 80202

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Buck, Paul	303-882-5868	pbuck@bisonog.com	ALL INSPECTIONS
Milne, Rachel	720-370-8580	rmilne@bisonog.com	
Garza, Tarah	970-514-3581	tgarza@bisonog.com	Environmental Compliance Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
461134	Location	AC			-	WILSON PC GQ 02-04	AC

General Comment:

This is a Tank Battery Field Compliance Audit

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate - Cover up the previous Operator's Contact Phone Number		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Barbed Wire		
Corrective Action:			Date:

Equipment:

Type	#		corrective date
Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:	<input type="text"/>				

Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Share berm with the Crude Oil Tanks						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Share berm with the Crude Oil Tanks						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 461134 Type: Location API Number: - Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696307677	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7072652