

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2025

Submitted Date:

05/29/2025

Document Number:

696307684

FIELD INSPECTION FORMLoc ID 461104 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10670

Name of Operator: BISON IV OPERATING LLC

Address: 518 17TH STREET SUITE 1800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Milne, Rachel	720-370-8580	rmilne@bisonog.com	
Buck, Paul	303-882-5868	pbuck@bisonog.com	ALL INSPECTIONS
Garza, Tarah	970-514-3581	tgarza@bisonog.com	Environmental Compliance Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
461104	Location	AC			-	BASHOR PC GQ 15-13	AC

General Comment:

This is a Tank Battery Field Compliance Audit

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate - Cover up previous Operators Phone Number at Entrance and Tank Battery Signs; see photos		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Vertical Separator	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:			Date:	
Type: Vertical Heater Treater	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					

Corrective Action:						Date:				
<u>Paint</u>										
Condition		Adequate								
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:						Shares berm with the Crude Oil Tanks				
Corrective Action:								Date:		
Contents		#	Capacity		Type		Tank ID		SE GPS	
CRUDE OIL		1	500 BBLs		STEEL AST				,	
Comment:										
Corrective Action:								Date:		
<u>Paint</u>										
Condition		Adequate								
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Metal		Adequate		Walls Sufficient		Base Sufficient		Adequate		
Comment:										
Corrective Action:								Date:		
Contents		#	Capacity		Type		Tank ID		SE GPS	
PRODUCED WATER		1	500 BBLs		STEEL AST				,	
Comment:										
Corrective Action:								Date:		
<u>Paint</u>										
Condition		Adequate								
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:						Shares berm with the Crude Oil Tanks				
Corrective Action:								Date:		
<u>Venting:</u>										

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	461104	Type:	Location	API Number:	-	Status:	AC	Insp. Status:	AC
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="SI - Shut-In at the time of this Field Audit"/>									
Corrective Action: <input type="text"/> Date: _____									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696307685	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7072656