

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2025

Submitted Date:

05/29/2025

Document Number:

713302091**FIELD INSPECTION FORM**Loc ID 318475 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241368	WELL	SI	05/01/2021	OW	123-09157	COSSLETT A 9	SI

General Comment:[follow up well site inspection](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	electric disconnect, metal panels		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 1		
Comment:	pipd to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	automation/electric panels		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 241368 Type: WELL API Number: 123-09157 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: well shut in 5-1-21
Mechanical integrity Testing, Rule 417b, corrective action date 4-29-2024
have NOT been addressed.

Corrective Action: comply with Rule 417bDate: 04/29/2024**BradenHead**Date of Last Brhd Test: 06/05/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 42 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary Inspector Michael Kester, conducted an on-site Follow up inspection as per doc# 713301341 in accordance with Rule 901a, corrective actions appeared to have NOT been addressed</p> <p>Location: Cosslett A9 Operator: KPK API#: 123-09157 County: Weld</p> <p>Mechanical integrity Testing, Rule 417b, corrective action date 4-29-2024</p> <p>Weather conditions: clear and dry</p> <p>This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	05/29/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302092	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7073668