

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2025

Submitted Date:

05/23/2025

Document Number:

708906540

FIELD INSPECTION FORMLoc ID 335202 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

33 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Ramsey, Scott		scott.ramsey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211390	WELL	PR	06/27/1997	GW	045-07150	GIBSON GULCH UNIT 6-29	PR
288308	WELL	PR	09/01/2018	GW	045-13188	GGU DALEY 22A-29-691	PR
288311	WELL	PR	06/22/2007	GW	045-13185	GGU DALEY 12D-29-691	PR
288312	WELL	PR	06/20/2007	GW	045-13184	GGU DALEY 21A-29-691	PR

General Comment:**CECMC Inspection/Audit Report Summary**

On 05/22/2025 at approximately 12:48 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location # 335202 in Garfield County Colorado.

Location is within High Priority/Density/NSO/Black Bear Habitat areas.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Stormwater - Failure to minimize erosion & transport of sediment off location/insufficient BMP's with a CA date of 06/07/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Sign at gate on lease road		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	2 signs weathered & some required info is starting to fade		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused hose in secondary containment - please refer to photo log		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pig station - cattle panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:	Supply gas line connected to ECD Piping from battery disconnected		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Taylor plugs located on bradenheads, bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	1 marked deadman 1 unmarked deadman All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		

Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:	Tanks not equipped with telemetry					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,	
Comment:	Tanks not equipped with telemetry					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 211390 Type: WELL API Number: 045-07150 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/17/2025Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 151 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: BH line connected to flowline - FORM 4 SUNDRY document # 402555183Ball valve on line connecting BH line to flowline appears to be shut - please refer to photo log

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 288308 Type: WELL API Number: 045-13188 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 288311 Type: WELL API Number: 045-13185 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 288312 Type: WELL API Number: 045-13184 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Gravel				Sparse to none
		Compaction				Light compaction in some sections
Gravel						Sparse to none
		Check Dams				Sediment buildup at BMP's
		Ditches				
Compaction						Light compaction in areas
Other	Fail					Erosion & transport of sediment off location
		Culverts				
Berms						

Comment: 1. Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Additionally sediment being transported off location is choking off vegetation

Corrective Action: Comply with CECMC Stormwater rules

Date: 06/07/2025

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Stormwater for corrective action & also refer to Housekeeping, Equipment & Inspected Facilities for comments.	smelserw	05/23/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404216288	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7063161
708906541	Inspection/Audit 708906540 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7063159
708906542	Inspection/Audit 708906540 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7063160