

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2025

Submitted Date:

05/28/2025

Document Number:

717000366**FIELD INSPECTION FORM**Loc ID 319725 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201124	WELL	SI	06/01/2018	GW	001-06527	CHAMPLIN 78 AMOCO A 1	SI

General Comment:[Routine inspection / no change to equipment](#)

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:		<div>Adequate</div>		
Corrective Action:		<div></div>		Date: <div></div>
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:		<div></div>		
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: <div></div>
Flaring:				
Type				
Comment:				
Corrective Action:				Date: <div></div>

Inspected Facilities

Facility ID: 201124

Type: WELL

API Number: 001-06527

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: SI

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/07/2024

Annual Brhd Completed?

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to the surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine inspection	finkenbc	05/28/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000367	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7074600