

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2025

Submitted Date:

05/31/2025

Document Number:

708906617

**FIELD INSPECTION FORM**

Loc ID: 335234    Inspector Name: Smelser, Wayne    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10550  
Name of Operator: MUSTANG RESOURCES LLC  
Address: 3 GREENWAY PLAZA STE 1360  
City: HOUSTON    State: TX    Zip: 77046

**Findings:**

20 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Mustang		nwelch@venatorresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210799	WELL	PR	07/01/2024	CBM	045-06557	MEAD 24-14MV-6S-94W	PR
210812	WELL	PR	01/01/2025	GW	045-06570	MEAD 24-14W-6S-94W	PR

**General Comment:**

[CECMC Inspection/Audit Report Summary](#)  
On 05/29/2025 at approximately 12:10 hours, I, Compliance Specialist, Wayne Smelser  
Conducted a follow up inspection/audit at MUSTANG RESOURCES LLC Mead 24-14MV Pad  
Location # 335234 in Garfield County Colorado.  
Please refer to inspection 708906416 conducted on 05/05/2025, previous corrective action has been completed.  
Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost site & in close proximity to NSO Habitat area.  
Location is approximately 333 yards from Beaver Creek.  
While there, I observed normal production operations.

This is a summary of inspection/audit report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/888-291-8588		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 2		corrective date

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	MEAD 24-14MV-6S-94W well on plunger lift MEAD 24-14W-6S-94W well is not on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	No form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 7		
Comment:	6 Marked deadman  1 Improperly marked deadman - please refer to photo log  All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	90 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	STEEL AST		,
Comment:	Tank not equipped with telemetry				

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment: <a href="#">Centralized containment</a>					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 210799 Type: WELL API Number: 045-06557 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 210812 Type: WELL API Number: 045-06570 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well not on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in areas
Compaction						Small amount of light compaction
		Compaction				
Other						Small gravel stockpile on location
		Gravel				Sparse to none

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Housekeeping &amp; Equipment for comments</a>	smelserw	05/31/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708906618	Inspection/Audit 708906617 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7076449">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7076449</a>
708906619	Inspection/Audit 708906617 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7076450">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7076450</a>