

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2025

Submitted Date:

06/02/2025

Document Number:

710500528**FIELD INSPECTION FORM**Loc ID 484358 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10797Name of Operator: DESERT EAGLE OPERATING LLCAddress: 17330 PRESTON RD STE 200D-208City: DALLAS State: TX Zip: 75252**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Bulf, Cathy		cathybulf@gmail.com	Desert Eagle Operating llc
Butler, Brad	972-345-9195	butleroil@yahoo.com	Desert Eagle Operating llc

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484677	WELL	PR	11/28/2023	HE	071-09931	Red Rocks 1-16	EI

General Comment:

This is an Environmental Inspection for the Red Rocks 1-16 well location located in Las Animas County, Colorado. Remediation Project # 33149

Location

Lease Road:			
Type	Access		
comment:	Access road is a graveled road through rangeland		
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well placard located at wellhead		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		
Lube Oil				
Comment:	At the time of inspection, oil stained soils were observed at Lat 37.464927; Long - 103.518785.			
Corrective Action:	The Operator shall investigate stained soils to determine the extent, makeup, and source of oily material in accordance with Rule 912.b.			Date: 05/29/2025

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	At the time of inspection fence panels at the wellhead were not secured. Comply with Rule 603.h.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	484677	Type:	WELL	API Number:	071-09931	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental		
Spill/Remediation:		
Comment:	<p>This is an Environmental Inspection for Remediation Project # 33149. At the time of inspection red stained soils were observed at Lat 37.461730; Long -103.518803. Operator shall collect confirmation soils samples from this area and areas exhibiting the highest degree of impacts for remediation project # 33149 going forward.</p> <p>Operator shall continue quarterly reporting until the remediation areas meets Table 915-1 standards for soils. Additional Sampling is needed to determine the extent of impacts to soils</p>	
Corrective Action:	Operator shall continue quarterly reporting in accordance with Rule 913.e	Date: 08/04/2025
Emission Control Burner (ECB): _____		
Comment:	_____	
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500529	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7077140