

# Inspection Photos

Loc: 321831

Operator: **P O & G OPERATING LLC**

Inspection Date: 5/28/2025

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast toward the tank battery.



## Inspection Photos



**Photo 2.** Facing southwest toward the well site and pumpjack.



## Inspection Photos



**Photo 3.** There are oil stained soils at the base of the pumpjack that need to be cleaned up and properly disposed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 5/28/2025

## Inspection Photos



**Photo 4.** There is oily fluid in this secondary containment of the chemical barrel with no wildlife protections. This needs to be netted to prevent wildlife entry.



## Inspection Photos



**Photo 5.** There is stained soils at the wellhead that need to be cleaned up and properly disposed. There is a leak at the wellhead that needs to be fixed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 5/28/2025

## Inspection Photos



**Photo 6.** Unused equipment stored on location needs to be removed.



## Inspection Photos



**Photo 7.** Facing toward the tank battery. Some of the labels are faded and missing information.



Inspection Photos



**Photo 8.** Facing northeast at the tank battery facility. Sign has been installed.



Inspection Photos



**Photo 9.** View of inside the shed shows oil stained soils and improper spill containment.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 5/28/2025

## Inspection Photos



**Photo 10.** Facing northeast past the shed. There was a spill that occurred which leaked out both inside and outside of secondary containment in this area. There is now water pooling in this area.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 5/28/2025

Inspection Photos



**Photo 11.** Facing northeast. It appears more impacted material was pushed out to the northeast corner pile.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 5/28/2025

## Inspection Photos



**Photo 12.** There is a pile of gravelly sand material stored at the northeast corner of the location. There is stained material incorporated into the pile. E&P waste must be stored with containment and liner.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 5/28/2025