

TEP
KP 23-16
Location ID: 335447



Location



Location

TEP
KP 23-16
Location ID: 335447



Location



Location

TEP
KP 23-16
Location ID: 335447



Recent inspection of tank battery signage still illegible.



Previous inspection

TEP
KP 23-16
Location ID: 335447



Recent photo of cap on tank load line



Previous inspection

TEP
KP 23-16
Location ID: 335447



Previous inspection of lack of stabilization and waddles failing



Lack of stabilization on cut slope/BMP's need maintenance

TEP
KP 23-16
Location ID: 335447



Previous inspection of lack of stabilization and waddles failing



Lack of stabilization on cut slope/BMP's need Maintenance. Top of cut slope is under mining with vegetation roots exposed.

TEP
KP 23-16
Location ID: 335447



Lack of stabilization on cut slope/BMP's need maintenance



Lack of stabilization on cut slope/BMP's need maintenance

TEP
KP 23-16
Location ID: 335447



Lack of stabilization on cut slope/BMP's need maintenance



Lack of stabilization on cut slope/BMP's need maintenance

TEP
KP 23-16
Location ID: 335447



Lack of stabilization on cut slope/BMP's need maintenance



Lack of stabilization on cut slope/BMP's need maintenance