

Inspection Photos
Location: Stavely 1-26
Location ID: 324837
API # 05-061-06394



Photo 1 –Well placard, Wrong API # listed on well placard, second CA for API #

Photo 2 – Wellhead and Pump Jack

Inspection Photos
Location: Stavely 1-26
Location ID: 324837
API # 05-061-06394



Photo 3 – Impacted soils at rear of pumping unit

Photo 4 – Photo from 2/24/2025

Inspection Photos
Location: Stavely 1-26
Location ID: 324837
API # 05-061-06394



Photo 5 – Tank Battery

Photo 6 – Leaking valve repaired