

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/02/2025

Submitted Date:

06/02/2025

Document Number:

710500530

**FIELD INSPECTION FORM**

Loc ID 324837 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Justin		Justin@strachanexploration.com	<a href="#">Strachan Exploration</a>
L, Stacy		stacy@strachanexploration.com	<a href="#">Field inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213033	WELL	SI	12/01/2024	OW	061-06394	STAVELY 1-26	EI

**General Comment:**

This is a follow-up Environmental Inspection to Inspection Document # 710500428 for the Stavely 1-26 well location, API # 05-061-06394, located in Kiowa County, Colorado

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wrong API # listed on the well placard located at the wellhead Original Corrective Action date of 4-24-2025 shall apply:  Install sign to comply with Rule 605.d.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Fencing at the pump jack not maintained.  Per FIRR response in FIRR Doc # 403985762: Fence was removed from around the pump jack while repairs were being done to the engine. Livestock has been removed from the field and landowner has told us there will be no more livestock on the property. We will eventually remove all of the fencing as it is no longer required. We have requested a letter outlining the land use. rigged up a temporary gate at the battery		
Corrective Action:	Repair Fencing in accordance with Rule 603.h. or supply surface owner agreement updating land use agreement	Date:	06/13/2025

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 213033 Type: WELL API Number: 061-06394 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Leaking valve observed on 2/24/2025 appears to have been repaired.  At the time of inspection there was a leak observed on a valve between the separator and tank. Lease Operator, Wayne, who was on a neighboring location was informed of leak on 2/24/2025, 1:28 p.m.	sanchezcc	06/02/2025
Stained soils at the rear of the Pump Jack have been removed.	sanchezcc	06/02/2025
All previous Corrective Actions not addressed shall apply	sanchezcc	06/02/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500531	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7078596">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7078596</a>