

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2025

Submitted Date:

05/27/2025

Document Number:

717100211

FIELD INSPECTION FORMLoc ID 318552 Inspector Name: Rollins, Grace On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Graber, Nikki		nikki.graber@state.co.us	
Brown, Kari		kari.oakman@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
490099	SPILL OR RELEASE	CL	05/08/2025		-	Strear Sidney GU1 Facility Hist Rel	EI

General Comment:**ECMC Field Inspection Report Summary**

This is an environmental inspection to determine progress on Spill ID 490099 and Remediation Project # 34642. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 490099

Spill Name: Strear Sidney GU1 Facility Hist Rel

Remediation Project #: 34642

Facility ID: 448084

Date of Discovery: 05/07/2025

Date of Inspection: 05/16/2025

The facility shares a location with Facility ID 448083, which will be addressed in a separate inspection.

Current site status:

- Two excavations remain open in the areas of the former separator and the former produced water vessel.
- No environmental impacts were visible in situ and no groundwater was observed in the open excavations.
- Weeds are visible in both excavations.
- Debris is visible in the excavation in the area of the former produced water vessel.
- Orange construction fencing surrounds the open excavations.
- Multiple unmarked soil stockpiles were observed on location with no stormwater BMPs. No liners were visible.

See attached corrective actions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds are visible in both excavations.		
Corrective Action:	Comply with Rule 606.		Date: 06/03/2025
Type	DEBRIS		
Comment:	Debris is visible in the excavation in the area of the former produced water vessel.		
Corrective Action:	Comply with Rule 606.		Date: 06/03/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Orange construction fencing surrounds the open excavations.		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	490099	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation Project # 34642 was created for decommissioning of the Strear Sidney GU1 Facility. Two excavations remain open in the areas of the former separator and the former produced water vessel. No environmental impacts were visible in situ and no groundwater was observed in the open excavations. Quarterly reporting is required under Remediation Project # 34642.

Corrective Action: _____

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
	Piles			
Comment	Multiple unmarked soil stockpiles were observed on location with no stormwater BMPs. No liners were visible.			
Corrective Action	Operator shall comply with Rule 913.b.(5).B.iv. and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil.			Date: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404218999	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7067085
717100212	ECMC Photo Log - Strear Sidney GU1 Facility Hist Rel - 05.16.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7067083