

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2025

Submitted Date:

05/27/2025

Document Number:

717100217

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Rollins, Grace On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	<a href="#">Staff Environmental Engineer</a>
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>
Mickelson, Erik		Erik_Mickelson@oxy.com	<a href="#">Oxy Environmental</a>
Brown, Kari		kari.oakman@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
490246	SPILL OR RELEASE	CL	05/19/2025		-	1415 Corp Gas Unit 2 Wellhead	EI

**General Comment:**

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 490246 and Remediation Project # 39909. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 490246

Spill Name: 1415 Corp Gas Unit 2 Wellhead

Remediation Project #: 39909

Wellhead API #: 05-123-10963

Date of Discovery: 5/15/2025

Date of Inspection: 05/20/2025

Spill is located within or adjacent to:

-Wetlands (Riverine, ~175 ft northwest)

-Crop land (immediately adjacent, all directions)

Current site status:

-Excavation remains open in the area of the former wellhead.

-No environmental impacts were visible in situ and no groundwater was observed in the open excavation.

-Debris was visible at the base of the excavation.

-Orange construction fencing surrounds the open excavation.

-Two exposed risers were visible within the excavation.

-An unmarked soil stockpile was observed on location; no liner was visible.

See attached corrective actions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type DEBRIS

Comment: Debris was visible at the base of the excavation.

Corrective Action: Comply with Rule 606.

Date: 06/03/2025

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type OTHER

Comment: Orange construction fencing surrounds the open excavation.

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 490246 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Remediation Project # 39909 was created for the plugging and abandonment of the 1415 Corp Gas Unit 2 Wellhead and decommissioning of the associated flowline. Excavation remains open in the area of the former wellhead. No environmental impacts were visible in situ and no groundwater was observed in the open excavation. Quarterly reporting is required under Remediation Project # 39909.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
	Piles			
	Comment	An unmarked soil stockpile was observed on location; no liner was visible.		
	Corrective Action	Operator shall comply with Rule 913.b.(5).B.iv. and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil.		Date: _____

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404218665	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7066715">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7066715</a>
717100218	ECMC Photo Log - 1415 Corp Gas Unit 2 Wellhead - 5.20.2025	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7066714">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7066714</a>