

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2025

Submitted Date:

05/27/2025

Document Number:

719000119**FIELD INSPECTION FORM**Loc ID 326558 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fields, Vanessa		vfields@logosresourcesllc.com	SJB inspections
Labowskie, Steve		steve.labowskie@state.co.us	
, General		Regulatory@logosresourcesllc.com	SJB inspect

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257222	WELL	PR	07/01/2019	GW	067-08297	IGNACIO 33-8 13R	PR

General Comment:

Inspection Report Summary
 On 5/27/25 I Inspector Charles Garcia
 conducted an on-site inspection.
 Location: IGNACIO 33-8 13R
 Operator: LOGOS OPERATING LLC
 API#: 067-08297
 County: LaPlata

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	125 BBL PRODUCED WATER TANK		
Corrective Action:		Date:	
Type	OTHER		
Comment:	LOCATION SIGN IN FRONT OF PRODUCED WATER TANK		
Corrective Action:		Date:	

Emergency Contact Number:

 Comment: 866-598-6220
 911 EMERGENCY

Corrective Action: _____ Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	125 BBL PRODUCED WATER TANK HOG WIRE		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:	LAST CALIABRATION 2/3/25		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		

Comment:	2 IN FLOW LINE ON NE EAST SIDE OF PRODUCED WATER TANK BULL PLUGED ON TOP BUT HAS NO TAG OUT OF SERVICE LINES MUST LOCKED OUT AND TAGED SEE LOCATION PICTURES			
Corrective Action:	TAG UNUSED FLOW LINE		Date:	06/27/2025
Type: Ancillary equipment	# 1			
Comment:	TELEMETRY EQUIPMENT			
Corrective Action:			Date:	
Type: Deadman # & Marked	# 0			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.064270,-107.414340
Comment:	PARTIALLY BURIED 125 PRODUCED WATER TANK				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	257222	Type:	WELL	API Number:	067-08297	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	05/07/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:	GAS				
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404219046	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7067204
719000120	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7067200