

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2025

Submitted Date:

06/03/2025

Document Number:

719000164

FIELD INSPECTION FORM

Loc ID 326496 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89098	WELL	PR	06/07/2001	CBM	067-08202	HUBER-LALONDE 4-31	PR

General Comment:

[Inspection Report Summary](#)
On 6/3/25 I Inspector Charles Garcia conducted an on-site inspection.
Location: HUBER-LALONDE 4-31
Operator:HILCORP ENERGY COMPANY
1-6 API#: 067-08202
County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SGIN AT ENTRANCE		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	505-324-5170 911 EMERGENCY		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	CATTLE PANLES		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	CATTLE PANLES		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Bird Protectors # 1			
Comment:			
Corrective Action:			Date:
Type: Flow Line # 1			
Comment:			
Corrective Action:			Date:
Type: Other # 1			
Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Ancillary equipment # 1			
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Ancillary equipment # 1			

Comment:	LUBE OIL CONTAINER FOR PRIME MOVER WITH SPILL PREVENTION		Date:
Corrective Action:			
Type: Prime Mover	# 1		
Comment:	GAS		Date:
Corrective Action:			
Type: Deadman # & Marked	# 4		
Comment:	ONE MARKER ON GROUND		Date:
Corrective Action:			
Type: Gas Meter Run	# 1		
Comment:	LAST CALIABRATION 3/10/25		Date:
Corrective Action:			
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			

Venting:

Yes/No	NO	Date:
Comment:		
Corrective Action:		

Flaring:

Type		Date:
Comment:		
Corrective Action:		

Inspected Facilities

Facility ID: 89098 Type: WELL API Number: 067-08202 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/08/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000165	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7080614