

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/28/2025

Submitted Date:

05/28/2025

Document Number:

719000134

FIELD INSPECTION FORM

Loc ID: 326438 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		Regulatory@logosresourcesllc.com	SJB inspect
Fields, Vanessa		vfields@logosresourcesllc.com	SJB inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216491	WELL	PR	07/01/2019	GW	067-08097	IGNACIO 33-7 3A	PR

General Comment:

Inspection Report Summary
On 5/28/25 | Inspector Charles Garcia conducted an on-site inspection.
Location: IGNACIO 33-7 #003A
Operator: LOGOS OPERATING LLC
API#: 067-08097
County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	125 PRODUCED WATER TANK		
Corrective Action:		Date:	
Type	OTHER		
Comment:	LOCATION SIGN ON METER HOUSE		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	866-598-6220 911 EMERGENCY		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	125 PRODUCED WATER TANK HOG WIRE		
Corrective Action:		Date:	
Equipment:			
			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	06/28/2025
Type: Other	# 1		
Comment:	METER HOUSE LAST CALIBRATION 2/6/25		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.038880,-107.355680
Comment:	125 PRODUCED WATER TANK Tank rusted , pitted, or peeling paint, or show evidence of inadequate repair. SEE LOCATION PICTURES				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 06/28/2025

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 216491 Type: WELL API Number: 067-08097 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Waddles	Fail					
Gravel	Pass	Gravel	Pass			

Comment: Stormwater management sediment and erosion control BMP'S ON NORTH WEST SIDE OF LOCATION FAILING CAUSING STORM WATER TO GO OVER AND UNDER EROSION AND BUILD UP OF SEDIMENT ON LOCATION SEE LOCATION PICTURES

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/28/2025

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404221094	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7068910
719000135	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7068902