

# Inspection Photos

## 05/07/2025

**Operator:** FULCRUM ENERGY OPERATING- #10805

**Location ID:** 463987

**Inspection Document #:** 712300116

## Jackson County, CO

Logan Maxwell  
Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: PRU Alcorn 0880 S10  
Location ID: 463987



**Photo 1.** Photo taken from entrance of the Location. Photo illustrates signage.



**Photo 2.** Photo taken from southwestern portion of the pad, facing northwest. Photo shows overview of location. A new OGDG for this Location is currently "in process" at time of inspection. The reclamation status of this Location is also considered "in process" pending the Commission's decision regarding the OGDG."



Inspection Photos  
Location Name: PRU Alcorn 0880 S10  
Location ID: 463987



**Photo 3.** Photo illustrates culvert at the entrance of the Location. No erosion issues observed at this time. However, the culvert does not appear to have been installed with inlet/outlet protections per good engineering practices.



**Photo 4.** Photo taken at the wellhead. The photo illustrates ponding water in the wellhead cellar.



Inspection Photos  
Location Name: PRU Alcorn 0880 S10  
Location ID: 463987



**Photo 5.** Photo taken of the topsoil stockpile. At this time, it does not appear enough topsoil was salvaged at the time of construction per 1002.b.



**Photo 6.** Photo taken of the topsoil stockpile. Maintain erosion matting to prevent degradation of the topsoil stockpiles.





Inspection Photos  
Location Name: PRU Alcorn 0880 S10  
Location ID: 463987



**Photo 7.** Photo taken at the northeastern portion of the pad, facing southeast. Photo illustrates the perimeter ditch. It is unclear if areas were included during previous reclamation/revegetation efforts conducted on the Location.



**Photo 8.** Photo taken at the eastern portion of the Location, facing the stormwater outlet. It is unclear if geotextile lining has been installed under the riprap per good engineering practices.





Inspection Photos  
Location Name: PRU Alcorn 0880 S10  
Location ID: 463987



**Photo 9.** Photo taken at the eastern portion of the Location. Photo illustrates an example of trash observed at the Location.



**Photo 10.** Photo taken at the southeastern portion of the Location. What appears to be cement waste has spilled on the location and perimeter berm.





Inspection Photos  
Location Name: PRU Alcorn 0880 S10  
Location ID: 463987



**Photo 11.** Photos 11-12 illustrate stained/impacted soils observed throughout areas on the pad. Remove and properly dispose of impacted material.



**Photo 12.** See comments on Photo 11.