

# Inspection Photos

**05/07/2025**

**Operator:** FULCRUM ENERGY OPERATING- #10805

**Location ID:** 467526

**Inspection Document #:** 712300119

Jackson County, CO

Logan Maxwell  
Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Spicer Annex S32 Pad  
Location ID: 467526



**Photo 1.** Photo taken from the entrance of the access road.



**Photo 2.** Photo taken from the entrance of the pad.

Inspection Photos  
Location Name: Spicer Annex S32 Pad  
Location ID: 467526



**Photo 3.** Photo taken from the northeastern portion of the pad, facing the eastern interim reclamation area. Photo illustrates seeding has occurred and straw mulch has been applied. It appears that straw mulch has densely accumulated in some areas. It may prevent early germination.



**Photo 4.** Photo taken from the northeastern portion of the pad, facing the eastern interim reclamation area. Photo illustrates seeding has occurred and straw mulch has been applied. Observed are areas where mulch does not appear to have been sufficiently anchored and has blown off.

Inspection Photos  
Location Name: Spicer Annex S32 Pad  
Location ID: 467526



**Photo 5.** Photo taken from the northwestern portion of the location, facing topsoil stockpile. Topsoil has been stabilized with erosion matting.



**Photo 6.** Photo taken from western portion of the location, facing south towards stockpiled soil. Erosion matting has been applied to soil stockpile.

Inspection Photos  
Location Name: Spicer Annex S32 Pad  
Location ID: 467526



**Photo 7.** Photo taken from western portion of location, facing northeast. It is unclear if all areas not needed for production have been reclaimed.



**Photo 8.** Photo taken from southeastern portion of Location of the tanks. Photo illustrates an example of missing caps/covers that prevent access to wildlife.