

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/20/2025

Submitted Date:

05/29/2025

Document Number:

718100535

FIELD INSPECTION FORMLoc ID 312407 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10150

Name of Operator: BLACK HILLS PLATEAU PRODUCTION LLC

Address: 1515 WYNKOOP ST STE 500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Maxwell, Logan		logan.maxwell@state.co.us	
Gaasche, Emily		emily.gaasche@state.co.us	
Kimble, Casey		casey.kimble@blackhillscorp.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221510	WELL	PA	08/21/2013	GW	077-08111	KATHLYN YOUNG 4-15	PA
312407	LOCATION	CL			-	KATHLYN YOUNG-610S95W 15NWSE	RI

General Comment:

On 5/20/2025, Western Reclamation Work Lead Trujillo and Northwest Reclamation Specialist Gaasche conducted a Final Reclamation inspection at BLACK HILLS PLATEAU PRODUCTION LLC's KATHLYN YOUNG #4-15 location in Mesa County, Colorado.

Location is within the following High Priority Habitats: Elk Winter Concentration Area.

This inspection is a follow-up to #696204939 dated 5/15/2023 and #696205299 dated 9/27/2023 to document compliance with the following corrective actions:

- Final Reclamation
- Stormwater

It was observed in this inspection that the Location remains out of compliance with ECMC Rules and Corrective Actions

Refer to the Reclamation and Stormwater section of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Inspected Facilities									
Facility ID:	221510	Type:	WELL	API Number:	077-08111	Status:	PA	Insp. Status:	PA
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	312407	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded Fail Contoured Fail Culverts removed _____

Gravel removed Fail

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured Fail

Compaction alleviation Fail Dust and erosion control Fail

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: [See "COGCC Comments" at the end of this report.](#)

Corrective Action: _____ Date _____

Overall Final Reclamation In Process Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See "COGCC Comments" at the end of this report.](#)

Corrective Action: [CA Per inspection #696204939](#)

Comply with Rule 1002.f and install and maintain stormwater and erosion control BMPs to minimize erosion, degradation and off-site sediment transport. Ensure BMPs are implemented to stabilize the seeded soils; stormwater management required until Location receives a passing final reclamation inspection.

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Several wildlife caracases were observed throughout the Location; within the southern end of the flat areas of the well pad, as well as the fill slopes.	trujilloam	05/29/2025
RECLAMATION AND STORMWATER COMMENT Previous inspections observed that Final Reclamation of the Location was not complete in accordance with 1004 Rules; Location has not been recontoured/regraded and reclaimed. Cut and fill slopes evident; Cut slopes lack stabilization and erosion degradation was observed. A soil stockpile was observed on the southern areas of the Location; segregated soils have not been replaced to their original relative positions and contoured. Gravel and road base material remains apparent on Location; access road has not been decompacted, recontoured/regraded and reclaimed; unused pipe equipment remained stored on the Location. Inspections required Operator to comply with Rules 1004 and 1002.f by 7/17/2023. It was observed in this inspection that the Location has not been reclaimed, pipe equipment has not been removed, and stormwater and erosion control BMPs have not been installed or maintained; slopes on the Location remain bare and unstabilized- erosion degradation has persisted on the Location and access road. Operator filed a hearings application (docket #240100018) with a 502.b surface owner variance request from ECMC Rules 1004.c. (2-3), 1004.d. and 1004.e; for the Location and access road to be left in its current state. The overall status of the Reclamation is being considered "in process" pending the Commission's decision, and resolution of the Variance Hearing Application. The corrective actions related to stormwater management remains applicable.	trujilloam	05/29/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404222916	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7073572
718100536	Inspection Photos and Drone Report	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7073570