

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2025

Submitted Date:

06/05/2025

Document Number:

694500773

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 2 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 10779
 Name of Operator: SCOUT ENERGY MANAGEMENT LLC
 Address: 13800 MONTFORT DRIVE SUITE 100
 City: DALLAS State: TX Zip: 75240

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Christian, Cody	970-902-0518	Cody.Christian@scoutep.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488590	SPILL OR RELEASE	CL	03/11/2025		-	GRAY B 17 Flowline	EI

General Comment:
 On 6/4/25 ECMC staff, Kris Neidel inspected the Gray B17 spill, number 488590. Any corrective actions issued by ECMC in other inspections remain valid. Weather was 75 degrees and partly cloudy. The following was observed: the subsurface point of release had been backfilled, much of the impacted vegetation in the spill path appeared alive and free of hydrocarbon, there were a few areas of isolated hydrocarbon staining, less than one sq foot. Corrective Actions: remove areas of observable hydrocarbon staining with a shovel and bucket (or equivalent, large equipment is not necessary and may inflict more damage). See attached photos.

Inspected Facilities

Facility ID: 488590 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: there were a few areas of isolated hydrocarbon staining, less than one sq foot.

Corrective Action: remove areas of observable hydrocarbon staining with a shovel and bucket (or equivalent, large equipment is not necessary and may inflict more damage). Date: 06/26/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500774	photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7083861