

Inspection Photos
Location: Rhoades Unit Gas Injection Flowline
Location ID: 476172
Spill ID # 489565



Photo 1 – Placard at facility

Photo 2 – Stained ground

Inspection Photos
Location: Rhoades Unit Gas Injection Flowline
Location ID: 476172
Spill ID # 489565




Photo 3 – Stained Ground

Photo 4 – Impacted soils identified at Latitude 38.87975; Longitude -102.813523

Inspection Photos
Location: Rhoades Unit Gas Injection Flowline
Location ID: 476172
Spill ID # 489565



Photo 5 – Impacted materials

Photo 6 – Impacted materials