

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2025

Submitted Date:

06/05/2025

Document Number:

710500537

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 17180
 Name of Operator: CITATION OIL & GAS CORP
 Address: 14077 CUTTEN RD
 City: HOUSTON State: TX Zip: 77069

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	COGC
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	COGC
Longworth, Mike		mike.longworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
255968	GAS PROCESSING PLANT	AC			-	MPU Press Maint and Inject Facility	EI
489244	SPILL OR RELEASE	AC	03/10/2025		-	MPU Gas Processing Plant - Tank	EI
489245	SPILL OR RELEASE	AC	03/10/2025		-	MPU Gas Processing Plant - Wellhead	EI

General Comment:

This is a follow up Environmental Inspection for the MPU Press Maint and Inject Facility, Facility ID 255968, Spill Facility ID 489244, and Spill Facility ID 489245.

Inspected Facilities

Facility ID: 255968 Type: GAS API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 489244 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 489245 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: This is a follow up environmental inspection for Spill ID 489244 and Spill ID 489244, Both Facilities are beyond the 90-day closure window per Rule 912.b(6). At the time of inspection Spill Remediation was ongoing for Spill ID 489244 and Spill 489244.
 Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure. The Form 19 Supplemental Report for closure was due by April 29, 2025

Corrective Action: **Operator shall submit delinquent form(s) for this project.**
Comply with Rule 912.b.(6) Date: 06/19/2025

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500538	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084370