

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2025

Submitted Date:

06/05/2025

Document Number:

710500539

FIELD INSPECTION FORM

Loc ID 476172 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96730
Name of Operator: WILLIFORD ENERGY COMPANY
Address: 6060 AMERICAN PLAZA SUITE 760
City: TULSA State: OK Zip: 74135

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Storts, Doug	(918) 495-2710	pds@willifordenergy.com	
Longworth, Mike		mike.longworth@state.co.us	
Growns, Larry		lgrowns@willifordenergy.com	
Pamela Richards		prichards@willifordenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476172	LOCATION	AC			-	Rhoades Unit Gas Injection Flowline 3213S48W	EI
489565	SPILL OR RELEASE	AC	03/18/2025		-	Rhoades Unit Gas Injection Flowline	EI

General Comment:

[This is an Environmental Inspection for the Rhodes Unit Gas Injection Flowline located in Cheyenne County, Colorado, Spill ID 489565.](#)

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Placard at entrance to location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	
Other			
Comment:	At the time of inspection, impacted soils were observed at Latitude 38.87975; Longitude -102.813523 and Latitude 38.879750; Longitude -102.813523 Photo # 6		
Corrective Action:	Operator shall cleanup stained soils and securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>06/19/2025</u>

In Containment: No

Comment: _____

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 476172 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 489565 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: This is an Environmental Inspection for Spill ID 489565. Spill ID 489565 is beyond the 90-day closure window. Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure. The Form 19 Supplemental Report for closure was due by April 27, 2025. Remediation Project # 40325 is active. Operator shall submit a Form 19-s requesting closure for Spill ID 489565

Corrective Action: Operator shall submit delinquent form(s) for this project. Comply with Rule 912.b.(6) Date: 06/19/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)
------	------------	-----------	------------------

Oily Soil	Piles	Inadequate	
Comment	<p>Impacted soils stored on location, Per COA in Form 19-s Document # 403977643 for Spill ID 486489:</p> <p>Operator states under Corrective Actions: The impacted soil has been excavated and hauled to the bio-remediation at Williford's gas plant yard where it was placed in lined containment. The contaminated soil was fertilized and stirred until it was clean. Operator shall provide a waste manifest in accordance with Rule 905. b. for the transport of materials.</p> <p>In addition, the Operator shall provide evidence a Reuse and Recycling plan was approved for the treatment of E&P Waste at an off location Facility or provide a Facility Location ID for an approved E&P Waste Management Facility Per Rule 905.a.(3).</p>		

Corrective Action: Supply requested data per Rule 206. Date: 07/03/2025

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500540	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084371