

Inspection Photos  
Location: RHOADES UNIT TUBING FLOWLINE  
Location ID: 476137  
Spill ID(s) 486490, 489566, and 490098.



Photo 1 – Placard at facility

Photo 2 – Impacted Soils

**Inspection Photos**  
**Location: RHOADES UNIT TUBING FLOWLINE**  
**Location ID: 476137**  
**Spill ID(s) 486490, 489566, and 490098.**



**Photo 3 – Impacted Soils**

**Photo 4 – Impacted Soils**

Inspection Photos  
Location: RHOADES UNIT TUBING FLOWLINE  
Location ID: 476137  
Spill ID(s) 486490, 489566, and 490098.



Photo 5 – Impacted Soils

Photo 6 – Impacted Soils