

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2025

Submitted Date:

06/05/2025

Document Number:

710500541

FIELD INSPECTION FORM

Loc ID 476137 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 96730

Name of Operator: WILLIFORD ENERGY COMPANY

Address: 6060 AMERICAN PLAZA SUITE 760

City: TULSA State: OK Zip: 74135

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Richards, Pamela		prichards@willifordenergy.com	All Inspections
Storts, Doug	(918) 495-2710	pds@willifordenergy.com	
Costa, Ryan		ryan.costa@state.co.us	
Growns, Larry		lgrowns@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476137	LOCATION	AC			-	RHOADES UNIT TUBING FLOWLINE 3213S48W	EI
486490	SPILL OR RELEASE	AC	12/06/2024		-	RHOADES UNIT TUBING FLOWLINE	EI
489566	SPILL OR RELEASE	AC	03/18/2025		-	RHOADES UNIT TUBING FLOWLINE/3213S4	EI
490098	SPILL OR RELEASE	AC	05/09/2025		-	RHOADES UNIT TUBING FLOWLINE/3213S4	EI

General Comment:

This is an Environmental Inspection for the Rhodes Unit Tank Battery, Facility ID 476137, located in Cheyenne County, Colorado. Spill ID 486490, Spill ID 489566, and Spill ID 490098.

Inspected Facilities

Facility ID: 476137 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 486490 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 489566 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 490098 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: _____

Comment: This is an Environmental Inspection for Spill ID(s) 486490, 489566, and 490098. All spills are currently active with ongoing remediation. Spill ID 486490 is 346 days past the 90-day closure window per Rule 912.b.(6). Spill ID 489566 is 38 days past the 90-day closure window per Rule 312.b.(6) and Spill ID 490098, 10-day supplemental report is 21 days late per Rule 912.b.(4).

Corrective Action: Operator shall File a Form 27-i Remediation Workplan in accordance with Rule 912.b.(6) for the transfer of Spill Facility ID(s) 486490, 489566, and 490098 Date: 06/13/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

ECMC Comments

Comment	User	Date
All previously assigned Corrective Actions and Conditions of Approval shall apply.	sanchezcc	06/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500542	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084491