

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2025

Submitted Date:

06/06/2025

Document Number:

713400832

**FIELD INSPECTION FORM**Loc ID 312496 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Koch, Benjamin		bzkoch@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Toews, Wesley		wtoews@blm.gov	
, LARAMIE		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221780	WELL	PR	03/01/2018	GW	077-08382	HORSESHOE CANYON 2-34	PR

**General Comment:****CECMC Inspection/Audit Report Summary**

On 06/4/2025 at approximately 13:06 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at LARAMIE ENERGY LLC Horseshoe Canyon/2-34 Pad at Location ID #312496 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Equipment - Dehydrator housing is damaged and available for entry by wildlife with a CA date of 06/13/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign on meter house		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign is becoming illegible, refer to photos		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-891-6191/911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris north of wellhead, refer to photos		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Small amount of staining in meter house, refer to photos		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Pipe rail

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment: No form of pressure monitoring equipment. Bradenhead valve is accessible

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 1

Comment: Well on plunger lift

Corrective Action:

Date:

Type: Bird Protectors

# 1

Comment:

Corrective Action:

Date:

Type: Dehydrator

# 1

Comment: Dehydrator housing is damaged and available for entry by wildlife

Corrective Action: Comply with CECMC wildlife rules

Date: 06/13/2025

Type: Deadman # &amp; Marked

# 2

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment: Staining on side of tank, refer to photos Tank not equipped with telemetry					
Corrective Action:					Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity) 60 bbls

Other (Type)



Inspected Facilities									
Facility ID:	221780	Type:	WELL	API Number:	077-08382	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms						
		Berms				
		Compaction				Light compaction
Ditches						
		Ditches				
Compaction						Light compaction

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment for corrective action also Housekeeping, Tanks and Berms & Signs/Marker for comments.	popejoyd	06/06/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400833	Inspection-Audit Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7085383">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7085383</a>