



Inspection Photos
Location Name: UPRR 42 Pan Am F#4
Spill ID: 480343



Remedial excavation. Fencing is down, trash observed

Flowlines appear to have been replaced with ~3" HDPE flowline pipe at the surface.

Inspection Photos
Location Name: UPRR 42 Pan Am F#4
Spill ID: 480343



Torn fencing

Excavation



Inspection Photos
Location Name: UPRR 42 Pan Am F#4
Spill ID: 480343



Excavation. Torn fencing. Multiple flowlines of unknown status were observed exposed within the open excavation.

Excavation. Weeds. Torn fencing. Multiple flowlines of unknown status were observed exposed within the open excavation.

Inspection Photos
Location Name: UPRR 42 Pan Am F#4
Spill ID: 480343



Torn fencing



Torn fencing

Inspection Photos
Location Name: UPRR 42 Pan Am F#4
Spill ID: 480343




Flowlines appear to have been replaced with ~3" HDPE flowline pipe at the surface.

Torn fencing

Inspection Photos
Location Name: UPRR 42 Pan Am F#4
Spill ID: 480343



Weeds within the excavation



Multiple flowlines of unknown status were observed exposed within the open excavation.

Inspection Photos
Location Name: UPRR 42 Pan Am F#4
Spill ID: 480343



Trash

Inspection Photos
Location Name: UPRR 42 Pan Am F#4
Spill ID: 480343



Trash

Trash