

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2025

Submitted Date:

06/06/2025

Document Number:

696307699

FIELD INSPECTION FORM

Loc ID 413934 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413934	LOCATION	AC			-	WELLS RANCH AF 06-13	AC

General Comment:

[This is a Tank Battery Inspection ONLY](#)

Location

Overall Good:

Signs/Marker:

Type BATTERY

Comment: Adequate

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type DEBRIS

Comment: Tumbleweeds at Gas Meters; see photos

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type TANK BATTERY

Comment: Panels - Gate at Tanks appears to have fallen down; Cattle got into berm and knocked berms walls down. (See Tanks for berms)

Corrective Action:

Date:

Equipment:

Type	#	corrective date
Gas Meter Run	# 2	
Horizontal Heater Treater	# 2	
Emission Control Device	# 3	

Comment:

Corrective Action:

Date:

Type: Horizontal Heater Treater # 2

Comment:

Corrective Action:

Date:

Type: Emission Control Device # 3

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV CONCRETE		

Comment:

Corrective Action:

Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	53 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		40.424810,-104.370040
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: Cattle got into Tank Battery - berms are compromised				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 07/11/2025

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 413934 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696307700	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7085720