

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GM 24-1 PAD

Location ID: 334878

Date: 05/28/2025



Photo # 7419 Entrance to location

Photo # 7439 New battery sign has incorrect access information/not in compliance with CECMC rules

Inspection/Audit Photos


Location: TEP ROCKY MOUNTAIN LLC GM 24-1 PAD

Location ID: 334878

Date: 05/28/2025



May 28, 2025 at 11:29:21 AM
+39.460832,-108.062656 ±4.32m
Parachute



May 28, 2025 at 11:37:45 AM
+39.460770,-108.062386 ±3.70m
Parachute

Photo # 7420 Location

Photo # 7428 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GM 24-1 PAD

Location ID: 334878

Date: 05/28/2025



Photo # 7436 Location



Photo # 7438 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GM 24-1 PAD

Location ID: 334878

Date: 05/28/2025



Photo # 7443 SE corner of location



Photo # 7444 NE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GM 24-1 PAD

Location ID: 334878

Date: 05/28/2025



Photo # 7445 NW corner of location



Photo # 7446 SW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC GM 24-1 PAD

Location ID: 334878

Date: 05/28/2025



Photo # 7432 Small amount of staining at GM 324-1 wellhead



Photo # 7435 Debris near wellheads