

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2025

Submitted Date:

06/02/2025

Document Number:

719000155**FIELD INSPECTION FORM**Loc ID 306993 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 7125Name of Operator: BEEMAN OIL & GAS INCAddress: 13635 E 104TH AVENUE STE 400City: COMMERCE CITY State: CO Zip: 80022**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Lawton, Lisa	(970) 846-4639	lisa@beemanoil.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Galloway, Kelly		kgallowaywerc@gmail.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292161	WELL	SI	11/01/2023	OW	067-09390	HUBBS 2	SI

General Comment:

[Inspection Report Summary](#)
[On 5/30/25 | Inspector Charles Garcia](#)
 conducted an on-site inspection.
 Location: [HUBBS #2](#)
 Operator: [BEEMAN OIL & GAS LLC](#)
 API#: [067-09390](#)
 County: [LaPlata](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	LOCATION SIGN IN FRONT OF ELECTRICAL PANEL Well sign displays incorrect API #		
Corrective Action:	Install sign that complies with rule 605.a ORIGINAL CA WAS DUE 11/8/24 DOCUMENT #714001324		Date: 07/02/2025

Emergency Contact Number:

Comment:	970-210-2896 911 EMERGENCY	
Corrective Action:		Date:

Good Housekeeping:

Type	WEEDS		
Comment:	WEEDS WITHIN 25FT OF GAS COMBUSTER AND ELECTRIC PANEL SEE LOCATION PICTURES		
Corrective Action:	REMOVE WEEDS WITHIN 25 FT OF EQUIPMENT RULE 605		Date: 07/02/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	OTHER		
Comment:	GAS COMBUSTER 4FT HOG WIRE		
Corrective Action:			Date:
Type	OTHER		
Comment:	ELECTRIC PANEL 4FT HOGWIRE		
Corrective Action:			Date:

Equipment:

Type: Prime Mover	# 1		corrective date
Comment:	ELECTRIC		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	ELECTRIC PANEL		
Corrective Action:			Date:
Type: Other	# 1		

Comment:	EELLHEAD		Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	GAS COMBUSTER		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Flow Line	# 2			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLs	PBV STEEL		37.123082,-108.109646
Comment:	REMOTE TANK BATTERY				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Encroaching weeds/vegetation affecting berm permeability at tank battery secondary PRAIRIE DOG BURROWS INSIDE CONTAINMENT SEE LOCATION PICTURES			
Corrective Action:	Maintain berms per rule 603.			Date: 07/02/2025

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	292161	Type:	WELL	API Number:	067-09390	Status:	SI	Insp. Status:	SI
BradenHead									
Date of Last Brhd Test:		04/21/2025		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type: NONE			
		End Surf Csg Pressure:		0					
Comment:		<div></div>							
Corrective Action:		<div></div>						Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404225948	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7078065
719000157	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7078038