

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2025

Submitted Date:

06/09/2025

Document Number:

719000185

**FIELD INSPECTION FORM**

Loc ID: 325589 Inspector Name: GARCIA, CHARLES On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96735  
Name of Operator: WILLIFORD RESOURCES LLC  
Address: 6506 S LEWIS AVE STE 102  
City: TULSA State: OK Zip: 74136

**Findings:**

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		glennstevens95@gmail.com	
Hubbard, Corky	806-658-9758 off/33825	whubbard@willifordenergy.com	806-435-0529 cell
Labowskie, Steve		steve.labowskie@state.co.us	
Growns, Larry		lgrowns@willifordenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215051	WELL	SI	02/01/2025	OW	067-06656	SCHMITT ESTATE 2-36	SI

**General Comment:**

Inspection Report Summary  
On 6/6/25 I Inspector Charles Garcia conducted an on-site inspection.  
Location: SCHMITT #2-36  
Operator: Simcoe LLC  
API#: 067-06656  
County: LaPlata

Location			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT PUMP JACK		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	918-712-8828 911 EMERGENCY		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	CATTLE PANLES		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	CATTLE PANLES		
Corrective Action:			Date:
<b>Equipment:</b>			
corrective date			
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	GAS		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215051 Type: WELL API Number: 067-06656 Status: SI Insp. Status: SI

**BradenHead**

Date of Last Brhd Test: 10/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
	garciacr1	06/06/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000186	LOCATION PICTURES	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7087151">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7087151</a>